


Port & Company[®] Youth Tie-Dye Pullover Hooded Sweatshirt. PC146Y

HOW TO MEASURE



CHEST WIDTH

Measure under the arm and around the fullest part of the chest with arms ${\sf dow}\, {\sf n}$, keeping tape horizontal.

SIZE CHART

		XS	s	М	L	XL
- +	Size	4	6/8	10/12	14/16	18/20
	Chest	25-26	26-28	28-30	30-32	32-35